

INSTRUCTIONS

WARNING: Tighten screws to 20 in lbs (2.3 Nm) of torque. To help prevent bottle launching, it is essential to ensure the bottle cage top hook fits snugly into the groove around the bottle, which must be continuous. When bottles show signs of wear, replace with new bottles.

ADDITIONAL COLOR Talons can be purchased separately for the Raptor cage. To replace the Talons, remove the two mounting screws holding the cage. The Talons on the top and bottom of the cage can slide off and replacement ones can be placed on. Make sure each of the Talon pieces is on the proper end of the cage so that the bottle can be held securely **Figure A**. Replace each of the mounting screws and torque to 20 in lbs (2.3 Nm) of torque.

NOTE: NOT GUARANTEED TO PREVENT BOTTLE LAUNCHING IN EVERY CONDITION



Figure A